Consult Your State DOT For The Most Up-To-Date Status Of Bridges

Structurally Deficient Bridges on the National Highway System

2nd Congressional District of Illinois, 2003

	Structure Number	Road	Location
1	000016006303727	I-57 NB	0.75 M S 127TH P4
2	000016008203755	I-80,94 KINGERY	2.3 M E ILL 394 P24
3	000016014903836	I-94 NB CALUMET	1.7 M SE I57 P8C
4	000016015103838	I-94 SB CALUMET	2 M SE I57 P8C
5	000016015203839	I-94 NB CALUMET	2 M SE I57 P8C
6	000016019903981	ILL1 HALSTED ST	1.5 M S US 6 P24
7	000016027404028	US-30/GLENWD-DYER	0.2 M SE US 30 P2
8	000016093504568	TORRENCE AVE	1.5 M N ILL 83 P24
9	000016204026356	MICHIGAN AVE	0.4 M SE I57 P8C
10	000016605026646	TORRENCE AVE	12440 S TORRENCE AVE
11	000016641603339	I-90 SKYWAY	0.22 M SE COMM AV
12	000016641805653	I-90 SKYWAY	VIAD, CALUMET RV
13	000016641905692	I-90 SKYWAY	VIAD, CALUMET RV
14	000016642005711	I-90 SKYWAY	VIAD, CALUMET RV
15	000016642105741	I-90 SKYWAY	0.19 M NW 100TH
16	000016642205766	I-90 SKYWAY	0.11 M NW 100TH
17	000016642305760	I-90 SKYWAY	AT 100TH ST
18	000016642405783	I-90 SKYWAY	0.07 M SE EWING
19	000016642905908	I-90 SKYWAY	0.44 M NW 106TH
20	000016643305990	I-90 SKYWAY	0.09 M NW 106TH
21	000016643406024	I-90 SKYWAY	0.03 M NW 106TH
22	000016643604706	I-90 SKYWAY EX RAM	105TH & INDPLS BL



Legend

- Structurally Deficient Bridges
- Cities
- Airports
- Amtrak Stations
- Interstate Highways
- US Highways
- State Highways
- Amtrak Routes
- Other Rail Lines
- Navigable Waterways
- Illinois District 2
- Urbanized Areas
- Park Facilities

N W E S

U.S. Department of Transportation
Bureau of Transportation Statistics
Federal Highway Administration

The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,643 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.