AMENDMENT TO H.R. 4441 OFFERED BY MR. ZELDIN OF NEW YORK

Beginning on page 183, strike line11 and all that follows through page 184, line 12 (and conform the table of contents accordingly).

At the end of subtitle A of title IV, add the following:

1	SEC. 4 SECONDARY COCKPIT BARRIERS IN NEW AIR-
2	CRAFT.
3	(a) In General.—Not later than 180 days after the
4	date of enactment of this Act, the Administrator of the
5	Federal Aviation Administration shall issue an order that
6	requires, for commercial passenger aircraft manufactured
7	for delivery to an air carrier in the United States begin-
8	ning 180 days after such order is published —
9	(1) on each covered aircraft the installation of
10	a barrier, other than the cockpit door, that prevents
11	access to the flight deck of the aircraft; and
12	(2) for a covered aircraft that is equipped with
13	a cockpit door, that the barrier required under para-
14	graph (1) remain locked while—
15	(A) the aircraft is in flight; and

1	(B) the cockpit door separating the flight
2	deck and the passenger area is open.
3	(b) COVERED AIRCRAFT DEFINED.—In this section,
4	the term "covered aircraft" means a commercial pas-
5	senger aircraft operating under part 121 of title 14, Code
5	of Federal Regulations.

 \times



f:\VHLC\021016\021016.218.xml

February 10, 2016 (2:59 p.m.)