Consult Your State DOT For The Most Up-To-Date Status Of Bridges

Structurally Deficient Bridges on the National Highway System

14th Congressional District of Illinois, 2003

	Structure Number	Road	Location
1	000022006105549	IL64	ILL 64 & W BR DUPAGE
2	000037003508433	FAI 80 EB	0.1 MI W JCT ILL 82
3	000037003708435	FAI 80 EB	S EDGE GENESEO
4	000037003808436	FAI 80 WB	S EDGE GENESEO
5	000045002610331	ILL 56 EB	.4M N OF GALENA BLVD
6	000045002710332	ILL 56 WB	.4M N OF GALENA BLVD
7	000045003510341	ILL 56 EB	4 MI S IL5(E-W TOLL)
8	000045003610342	ILL 56 WB	4 MI S IL5(E-W TOLL)
9	000045008208834	ILL 47	5 MI N OF IL 56
10	000047002210811	US 34	E LIMITS OF OSWEGO
11	000047003210821	US 30	0.5 MI W OF US 34
12	000052002111928	ILL ROUTE 26	0.25 MI S. OF I-88



Legend

- Structurally Deficient Bridges
- Cities
- Airports
- Amtrak Stations
- Interstate Highways
- US Highways
- State Highways
- Amtrak Routes
- Other Rail Lines
- Navigable Waterways
- Illinois District 14
- Urbanized Areas
- Park Facilities
- Military Bases

N
W E
S

U.S. Department of Transportation
Bureau of Transportation Statistics
Federal Highway Administration

The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,643 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.